

# ARKANSAS

ENERGY & ENVIRONMENT

RECEIVED  
19 AUG 26 AM 11:35

ENVIRONMENTAL QUALITY

SUPERFUND DIV.  
DIRECTOR'S OFC.

August 20, 2019

Stephen Pereira REP, CESCO, CNRP, MS (Life Scientist, Remedial Project Manager)  
U.S. Environmental Protection Agency (Region 6)  
Superfund Division (6SF-RA)  
1201 Elm St, Suite 500  
Dallas, TX 75270-2102

**Re: Old Midland Products Site, Ola, Arkansas, Spring and Fall 2018 Semi-Annual  
Groundwater Monitoring Reports**  
**EPA ID: ARD980745665** **AFIN 07-00049**

Dear Mr. Pereira:

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) is required to conduct the periodic Operations and Maintenance groundwater sampling at the Old Midland Products Superfund Site in Ola, Arkansas. Please find enclosed a CD copy of the Spring and Fall 2018 Semi-Annual Groundwater Monitoring Reports for the Old Midland Products for EPA review. The report documents the sampling activities, analytical results, and the conclusions and recommendations for Site operations and maintenance. Please contact me via e-mail at [wrightt@adeq.state.ar.us](mailto:wrightt@adeq.state.ar.us) or call 501-683-0068 with any questions or concerns.

Sincerely,



Tyler Wright  
Geologist  
Office of Land Resources

Encl

9456707



Division of Environmental Quality

5301 Northshore Drive, North Little Rock, AR 72118-5317  
[adeq.state.ar.us](http://adeq.state.ar.us)



# DEQ

KANSAS  
Department of Environmental Quality

NORTHSHORE DRIVE  
LITTLE ROCK, AR 72118-5317

Attn: Stephen Pereira, Remedial Project Manager  
U.S. Environmental Protection Agency (Region 6)  
Superfund Division (6SF-RA)  
1201 Elm St., Suite 500  
Dallas, TX 75270-2102



US POSTAGE AND FEES PAID

FIRST-CLASS

Aug 21 2019

Mailed from ZIP 72202

5oz First-Class Pkg Svc Zone 3




endicia

CID: 182415

CommercialBasePrice

071V01329092

USPS TRACKING #



9400 1102 0086 4701 0738 23